

USB FIRMWARE RELEASE NOTES

Alvium 1800 U cameras

2022-Jul-20
V00.10.00.6c9062b1

Helpful downloads

- Operating and updating cameras: Alvium USB Cameras User Guide
- Features: Alvium Features Reference
www.alliedvision.com/en/support/technical-documentation/alvium-usb-documentation
- Firmware files
www.alliedvision.com/en/support/firmware
- Firmware updater, included in **Vimba Suite**
www.alliedvision.com/software

Latest firmware version for your Alvium USB model

The following table lists the latest firmware version for your Alvium USB camera.

| Models | FW version | FW release date |
|--|--------------------------------------|-----------------|
| 1800 U-030 VSWIR, U-040m/c, U-050m/c, U-052m/c, U-120m/c, U-130 VSWIR, U-158m/c, U-235m/c, U-240m/c, U-291m/c, U-319m/c, U-500m/c, U-501m/c NIR, U-507m/c, U-508m/c, U-511m/c, U-811m/c, U-812 UV, U-1236m/c, U-1240m/c, U-1242m/c, U-1620m/c, U-2040m/c, U-2050m/c, U-2460m/c | FW 00.10.00.6c9062b1 | 2022-Jul-20 |

Table 3: Latest firmware version by model

FW 00.10.00.6c9062b1

Release date: 2022-Jul-20

Supported models

| Camera family | Model |
|---------------|--|
| Alvium 1800 | 1800 U-030 VSWIR, U-040m/c, U-050m/c, U-052m/c, U-120m/c, U-130 VSWIR, U-158m/c, U-235m/c, U-240m/c, U-291m/c, U-319m/c, U-500m/c, U-501m/c NIR, U-507m/c, U-508m/c, U-511m/c, U-811m/c, U-812 UV, U-1236m/c, U-1240m/c, U-1242m/c, U-1620m/c, U-2040m/c, U-2050m/c, U-2460m/c |

Table 4: Supported models

New models

Alvium 1800 U-235m/c, U-812 UV

Changed features

In previous firmware versions, **BlackLevel** values were adjusted to the pixel formats: 8-bit values for 8-bit pixel formats, 10 for 10, and 12 for 12. With this firmware update, the representation of **BlackLevel** is independent from the pixel format: 12-bit values are used for all pixel formats. Therefore, you may have to adjust your settings used with previous firmware versions.

The maximum value for **Gain** was increased from 24 to 48 dB for all models with Sony IMX global shutter sensors.

New features

- **ChunkDataControl** category
- **SequencerControl** category (The features in this category are still in the testing phase and not fully validated.)
- **SerialHub** subcategory for I/O control by UART
- **SoftwareSignalControl** subcategory to enable external devices to trigger actions within the camera by software commands (The features in this category are still in the testing phase and not fully validated.)

Known issues

| Alvium ID | Affected models | Description |
|-----------|---|--|
| 251 | U-2050m/c | If ShutterMode is changed after image acquisition, the ExposureActive signal disappears. |
| 253 | All | Auto mode feature IntensityControllerOutliersDark does not work properly. |
| 338 | U-500m/c, U-501 m/c NIR, U-1240m/c, U-2050m/c | If AcquisitionStop is executed shortly after AcquisitionStart , no image is transmitted. |

Table 5: Known issues

FW 00.08.01.13f227a4

Release date: 2022-May-16

Supported models

| Camera family | Model |
|---------------|--|
| Alvium 1800 | Alvium 1800 U-120m/c, U-500m/c, U-501m/c NIR |

Table 6: Supported models

New models

No new models were added

New features

No features were added.

Resolved issues

| Alvium ID | Affected models | Description |
|-----------|----------------------------|--|
| 775 | U-120c, U-500c, U-501c NIR | Wrong AutoWhiteBalance measurement was fixed. |

Known issues

| Alvium ID | Affected models | Description |
|-----------|---|--|
| 251 | U-2050m/c | If ShutterMode is changed after image acquisition, the ExpsoureActive signal disappears. |
| 253 | All | Auto mode feature IntensityControllerOutliersDark does not work properly. |
| 338 | U-500m/c, U-501 m/c NIR, U-1240m/c, U-2050m/c | If AcquisitionStop is executed shortly after AcquisitionStart , no image is transmitted. |

Table 7: Known issues

FW 00.08.00.6727174b

Release date: 2022-Mar-21

Supported models

| Camera family | Model |
|---------------|--|
| Alvium 1800 | U-030 VSWIR, U-040m/c, U-050m/c, U-052m/c, U-120m/c, U-130 VSWIR, U-158m/c, U-240m/c, U-291m/c, U-319m/c, U-500m/c, U-501m/c NIR, U-507m/c, U-508m/c, U-511m/c, U-811m/c, U-1236m/c, U-1240Um/c, U-1242m/c, U-1620m/c, U-2040m/c, U-2050m/c, U-2460m/c |

Table 8: Supported models

New models

Alvium 1800 U-052m/c, U-291m/c

New features

- Convolution filters in the **ImageProcessingControl** category
- Enabled all integer values from 1x to 8x for Digital Binning.
- **CounterAndTimerControl** category
- **ExposureActiveMode** (Rolling shutter (RS) models)
- **SensorBitDepth** (selected models)
- **UserSetControl**: Added individual user set options

Resolved issues

- No issues were fixed.

Known issues

| Alvium ID | Affected models | Description |
|-----------|---|--|
| 251 | U-2050m/c | If ShutterMode is changed after image acquisition, the ExposureActive signal disappears. |
| 253 | All | Auto mode feature IntensityControllerOutliersDark does not work properly. |
| 338 | U-500m/c, U-501 m/c NIR, U-1240m/c, U-2050m/c | If AcquisitionStop is executed shortly after AcquisitionStart , no image is transmitted. |

Table 9: Known issues

FW 00.07.00.81db3896

Release date: 2021-Dec-10

Supported models

| Camera family | Model |
|---------------|--|
| Alvium 1800 | U-030 VSWIR, U-040m/c, U-050m/c, U-120m/c, U-130 VSWIR, U-158m/c, U-240m/c, U-319m/c, U-500m/c, U-501m/c NIR, U-507m/c, U-508m/c, U-511m/c, U-811m/c, U-1236m/c, U-1240Um/c, U-1242m/c, U-1620m/c, U-2040m/c, U-2050m/c, U-2460m/c |

Table 10: Supported models

New models

Alvium 1800 U-030 VSWIR, U-130 VSWIR

New features

- Look-up tables (LUTs) features
- Sharpness/Blur
- TriggerDelay

Resolved issues

| Alvium ID | Affected models | Description |
|-----------|----------------------|---|
| 400 | U-1240m/c, U-2050m/c | If the TriggerSelector value is changed after acquisition, the ExposureActive signal disappears. |
| 401 | U-1240m/c, U-2050m/c | If TriggerSelector = FrameStart is turned off after streaming with TriggerSelector = FrameStart turned on, the camera shows an error code after stopping the stream. The camera must be rebooted. |

Table 11: Resolved issues

Known issues

| Alvium ID | Affected models | Description |
|-----------|---|--|
| 251 | U-2050m/c | If ShutterMode is changed after image acquisition, the ExposureActive signal disappears. |
| 253 | All | Auto mode feature IntensityControllerOutliersDark does not work properly. |
| 338 | U-500m/c, U-501 m/c NIR, U-1240m/c, U-2050m/c | If AcquisitionStop is executed shortly after AcquisitionStart , no image is transmitted. |

Table 12: Known issues

FW 00.06.00.35992

Release date: 2021-Aug-13

Supported models

| Camera family | Model |
|---------------|--|
| Alvium 1800 | U-040m/c, U-050m/c, U-120m/c, U-158m/c, U-240m/c, U-319m/c, U-500m/c, U-501m/c NIR, U-507m/c, U-508m/c, U-511m/c, U-811m/c, U-1236m/c, U-1240Um/c, U-1242m/c, U-1620m/c, U-2040m/c, U-2050m/c, U-2460m/c |

Table 13: Supported models

New models

Alvium 1800 U-511m/c, U-811m/c, U-1242m/c

New features

- Binning features
- DevicePowerSavingMode

Resolved issues

| Alvium ID | Affected models | Description |
|-----------|---------------------------------|--|
| 553 | U-1620m/c, U-2040m/c, U-2460m/c | Calculated frame rates for small ROIs are not exact. |

Table 14: Resolved issues

Known issues

| Alvium ID | Affected models | Description |
|-----------|---|--|
| 251 | U-2050m/c | If ShutterMode is changed after image acquisition, the ExposureActive signal disappears. |
| 253 | All | Auto mode feature IntensityControllerOutliersDark does not work properly. |
| 338 | U-500m/c, U-501 m/c NIR, U-1240m/c, U-2050m/c | If AcquisitionStop is executed shortly after AcquisitionStart , no image is transmitted. |
| 400 | U-1240m/c, U-2050m/c | If the TriggerSelector value is changed after acquisition, the ExposureActive signal disappears. |
| 401 | U-1240m/c, U-2050m/c | If trigger selector frame start is turned off after streaming with trigger selector frame start on, the camera will show an error code after stopping the stream. The camera must be rebooted. |

Table 15: Known issues

FW 00.04.00.34658

Release date: 2021-May-03

Supported models

| Camera family | Model |
|---------------|---|
| Alvium 1800 | U-040m/c, U-120m/c, U-158m/c, U-240m/c, U-319m/c, U-500m/c, U-501m/c NIR, U-507m/c, U-508m/c, U-1236m/c, U-1240Um/c, U-1620m/c, U-2040m/c, U-2050m/c, U-2460m/c |

Table 16: Supported models

New models

Alvium 1800 U-501c NIR, U-1620m/c, U-2040m/c, U-2460m/c

New features

- DeviceLinkCommandTimeout
- DeviceTLVersionMajor, DeviceTLVersionMinor
- Timestamp features

Known issues

| Alvium ID | Affected models | Description |
|-----------|---|--|
| 251 | U-2050m/c | If ShutterMode is changed after image acquisition, the ExposureActive signal disappears. |
| 253 | All | Auto mode feature IntensityControllerOutliersDark does not work properly. |
| 338 | U-500m/c, U-501 m/c NIR, U-1240m/c, U-2050m/c | If AcquisitionStop is executed shortly after AcquisitionStart , no image is transmitted. |
| 400 | U-1240m/c, U-2050m/c | If the TriggerSelector value is changed after acquisition, the ExposureActive signal disappears. |
| 401 | U-1240m/c, U-2050m/c | If trigger selector frame start is turned off after streaming with trigger selector frame start on, the camera will show an error code after stopping the stream. The camera must be rebooted. |
| 553 | U-1620m/c, U-2040m/c, U-2460m/c | Calculated frame rates for small ROIs are not exact. |

Table 17: Known issues

FW 00.03.00.31919

Release date: 2020-Dec-08

Supported models

| Camera family | Model |
|---------------|--|
| Alvium 1800 | U-040m/c, U-050m/c, U-120m/c, U-158m/c, U-240m/c, U-319m/c, U-500m/c, U-501m NIR, U-507m/c, U-508m/c, U-1236m/c, U-1240Um/c, U-2050m/c |

Table 18: Supported models

New models

No models were added.

New features

- Sensor timing optimizations increase maximum frame rates for selected models
- Updated default values for auto white balance
- Fixed pattern noise correction (FPNC) support for all models, except Alvium 1800 U-2050m/c
- Defect pixel correction (DPC, factory calibrated) for 1800 U-2050m/c models

Resolved issues

| Alvium ID | Affected models | Description |
|-----------|---------------------------------|--|
| 289 | All | Fixed wrong behavior of software triggers. |
| 299 | U-1236m/c, U-1240m/c, U-2050m/c | Fixed issue with AcquisitionStop command. |

Table 19: Resolved issues

Known issues

| Alvium ID | Affected models | Description |
|-----------|---|--|
| 251 | U-2050m/c | If ShutterMode is changed after image acquisition, the ExposureActive signal disappears. |
| 253 | All | Auto mode feature IntensityControllerOutliersDark does not work properly. |
| 338 | U-500m/c, U-501 m NIR, U-1240m/c, U-2050m/c | If AcquisitionStop is executed shortly after AcquisitionStart , no image is transmitted. |
| 400 | U-1240m/c, U-2050m/c | If the TriggerSelector value is changed after acquisition, the ExposureActive signal disappears. |
| 401 | U-1240m/c, U-2050m/c | If trigger selector frame start is turned off after streaming with trigger selector frame start on, the camera will show an error code after stopping the stream. The camera must be rebooted. |

Table 20: Known issues

FW 00.02.00.29974

Release date: 2020-Jul-23

Supported models

| Camera family | Model |
|---------------|--|
| Alvium 1800 | U-040m/c, U-050m/c, U-120m/c, U-158m/c, U-240m/c, U-319m/c, U-500m/c, U-501m NIR, U-507m/c, U-508m/c, U-1236m/c, U-1240Um/c, U-2050m/c |

Table 21: Supported models

New models

Alvium 1800 U-240m/c, U-508m/c, U-1240m/c

New features

No features were added.

Resolved issues

No issues were fixed.

Known issues

| Alvium ID | Affected models | Description |
|-----------|---|--|
| 251 | U-2050m/c | If ShutterMode is changed after image acquisition, the ExposureActive signal disappears. |
| 253 | All | Auto mode feature IntensityControllerOutliersDark does not work properly. |
| 289 | All | With default settings for software triggers, triggers can be missed. |
| 299 | U-1236m/c, U-1240m/c, U-2050m/c | AcquisitionStop command during sensor readout can stop camera. |
| 338 | U-500m/c, U-501 m NIR, U-1240m/c, U-2050m/c | If AcquisitionStop is executed shortly after AcquisitionStart , the captured frame is discarded. |

Table 22: Known issues

FW 00.01.03.29025

Release date: 2020-Mar-04

Supported models

| Camera family | Model |
|---------------|--|
| Alvium 1800 | U-040m/c, U-050m/c, U-120m/c, U-158m/c, U-319, U-500m/c, U-501m NIR, U-507, U-1236, U-2050 |

Table 23: Supported models

New models

Alvium 1800 U-319m/c, U-507m/c, U-1236m/c, U-2050m/c

New features

Defect pixel correction (DPC, factory calibrated, except for 1800 U-2050m/c models)

Resolved issues

| Alvium ID | Affected models | Description |
|-----------|-----------------|--|
| 79 | All | Fixed issues for <code>OffsetX</code> for <code>OffsetY</code> . |

Table 24: Resolved issues

Known issues

| Alvium ID | Affected models | Description |
|-----------|---------------------------------|--|
| 251 | U-2050m/c | If <code>ShutterMode</code> is changed after image acquisition, the <code>ExposureActive</code> signal disappears. |
| 289 | All | With default settings for software triggers, triggers can be missed. |
| 299 | U-1236m/c, U-1240m/c, U-2050m/c | <code>AcquisitionStop</code> command during sensor readout can stop camera. |

Table 25: Known issues

FW 00.01.02.28100

Release date: 2019-Dec-03

Supported models

| Camera family | Model |
|---------------|--|
| Alvium 1800 | U-040m/c, U-050m/c, U-120m/c, U-158m/c, U-500m/c, U-501m NIR |

Table 26: Supported models

New models

Alvium 1800 U-040m/c, U-158m/c, U-501m NIR

New features

- ColorTransformationMatrix
- Contrast
- ExposureActive signal
- Gamma
- Hue
- Saturation

Resolved issues

No issues were fixed.

Known issues

| Alvium ID | Affected models | Description |
|-----------|-----------------|---|
| 79 | All | Large values for OffsetX for OffsetY may not work properly. |

Table 27: Known issues

FW 00.01.01.27102

Release date: 2019-Oct-18

Supported models

| Camera family | Model |
|---------------|------------------------------|
| Alvium 1800 | U-050m/c, U-120m/c, U-500m/c |

Table 28: Supported models

New models

Alvium 1800 U-050m/c, U-120m/c

Resolved issues

No issues were fixed.

Known issues

No issues have been discovered.

FW 00.01.00.26405

Release date: 2019-Jul-01

Supported model

| Camera family | Model |
|---------------|----------|
| Alvium 1800 | U-500m/c |

Table 29: Supported models

New models

Initial commercial release of Alvium 1800 U-500m/c

Known issues

No issues have been discovered.

Contact us

Website, email

General

www.alliedvision.com/en/contact

info@alliedvision.com

Distribution partners

www.alliedvision.com/en/avt-locations/avt-distributors

Support

www.alliedvision.com/en/support

www.alliedvision.com/en/about-us/contact-us/technical-support-repair/-rma

Current firmware and release notes

<https://www.alliedvision.com/en/support/firmware-downloads>

Offices

**Europe, Middle East, and Africa
(Headquarters)**

Allied Vision Technologies GmbH
Taschenweg 2a
07646 Stadtroda, Germany
T// +49 36428 677-0 (Reception)
T// +49 36428 677-230 (Sales)
F// +49 36428 677-28

Asia-Pacific**China**

Allied Vision Technologies
(Shanghai) Co., Ltd.
2-2109 Hongwell Int. Plaza
1602# ZhongShanXi Road
Shanghai 200235, China
T// +86 21 64861133

Singapore

Allied Vision Technologies Asia Pte. Ltd
82 Playfair Rd, #07-01 D'Lithium
Singapore 368001
T// +65 6634 9027

North, Central, and South America**Canada**

Allied Vision Technologies Canada Inc.
300 – 4621 Canada Way
Burnaby, BC V5G 4X8, Canada
T// +1 604 875 8855

USA

Allied Vision Technologies, Inc.
102 Pickering Way- Suite 502
Exton, PA 19341, USA
Toll-free// +1-877-USA-1394
T// +1 978 225 2030