


Helpful downloads

- Operating and updating cameras: Alvium G1 Cameras User Guide
- Features: Alvium Features Reference
www.alliedvision.com/en/support/technical-documentation/alvium-gige-documentation
- Firmware files
www.alliedvision.com/en/support/firmware
- Firmware updater, included in **Vimba Suite**
www.alliedvision.com/software

Latest firmware version for your Alvium G1 model

The following table lists the latest firmware version for your Alvium G1 camera.

Models	FW version	FW release date
Alvium G1-040m/c, G1-158m/c, G1-234m/c, G1-240m/c, G1-319m/c, G1-500m/c, G1-507m/c, G1-811m/c, G1-1236m/c, G1-1242m/c, G1-1620m/c, G1-2040m/c, G1-2050m/c, G1-2460m/c	FW 00.10.00.2cf3b22e corrected	2022-Jul-20

Table 3: Latest firmware version by model

FW 00.10.00.2cf3b22e | corrected

Date of **corrections** for data in this document: 2022-Aug-08

Date of firmware release: 2022-Jul-20

Supported models

Corrected: Alvium **G1-235m/c** is not included.

Camera family	Model
Alvium	Alvium G1-040m/c, G1-158m/c, G1-234m/c, G1-240m/c, G1-319m/c, G1-500m/c, G1-507m/c, G1-811m/c, G1-1236m/c, G1-1242m/c, G1-1620m/c, G1-2040m/c, G1-2050m/c, G1-2460m/c

Table 4: Supported models

New model

Alvium G1-234m/c

Changed features

In previous firmware versions, **BlackLevel** values were adjusted to the pixel formats: 8-bit values for 8-bit pixel formats, 10 for 10, and 12 for 12. With this firmware update, the representation of **BlackLevel** is independent from the pixel format: 12-bit values are used for all pixel formats. Therefore, you may have to adjust your settings used with previous firmware versions.

Corrected: The maximum value for **Gain** is still **24 dB** for all models with Sony IMX global shutter sensors.

New features

- **ActionControl** category: The features are not working properly yet. This will be fixed in the next firmware release.
- **GVCP** subcategory
- **PTPCControl** category
- **SerialHub** subcategory for I/O control by UART
- **SoftwareSignalControl** subcategory to enable external devices to trigger actions within the camera by software commands (The features in this category are still in the testing phase and not fully validated.)

Known issues

Alvium ID	Affected models	Description
251	G1-2050m/c	If ShutterMode is changed after image acquisition, the ExposureActive signal disappears.
253	All	Auto mode feature IntensityControllerOutliersDark does not work properly.
338	G1-500m/c, G1-2050m/c	If AcquisitionStop is executed shortly after AcquisitionStart , no image is transmitted.

Table 5: Known issues

FW 00.10.00.2cf3b22e

Release date: 2022-Jul-20

Note: Data on this page is incorrect. Please see Chapter [FW 00.10.00.2cf3b22e](#) | [corrected](#) on page 2.

Supported models

Camera family	Model
Alvium	Alvium G1-040m/c, G1-158m/c, G1-234m/c, G1-235m/c, G1-240m/c, G1-319m/c, G1-500m/c, G1-507m/c, G1-811m/c, G1-1236m/c, G1-1242m/c, G1-1620m/c, G1-2040m/c, G1-2050m/c, G1-2460m/c

Table 6: Supported models

New models

Alvium G1-234m/c, G1-235m/c

Changed features

In previous firmware versions, **BlackLevel** values were adjusted to the pixel formats: 8-bit values for 8-bit pixel formats, 10 for 10, and 12 for 12. With this firmware update, the representation of **BlackLevel** is independent from the pixel format: 12-bit values are used for all pixel formats. Therefore, you may have to adjust your settings used with previous firmware versions.

The maximum value for **Gain** was increased from 24 to 48 dB for all models with Sony IMX global shutter sensors.

New features

- **ActionControl** category: The features are not working properly yet. This will be fixed in the next firmware release.
- **GVCP** subcategory
- **PTPControl** category
- **SerialHub** subcategory for I/O control by UART
- **SoftwareSignalControl** subcategory to enable external devices to trigger actions within the camera by software commands (The features in this category are still in the testing phase and not fully validated.)

Known issues

Alvium ID	Affected models	Description
251	G1-2050m/c	If ShutterMode is changed after image acquisition, the ExposureActive signal disappears.
253	All	Auto mode feature IntensityControllerOutliersDark does not work properly.
338	G1-500m/c, G1-2050m/c	If AcquisitionStop is executed shortly after AcquisitionStart , no image is transmitted.

Table 7: Known issues

FW 00.09.00.e23cb4e8

Release date: 2022-May-04

Supported models

Camera family	Model
Alvium	Alvium G1-040m/c, G1-158m/c, G1-240m/c, G1-319m/c, G1-500m/c, G1-507m/c, G1-811m/c, G1-1236m/c, G1-1242m/c, G1-1620m/c, G1-2050m/c, G1-2050m/c, G1-2460m/c

Table 8: Supported models

New models

Initial commercial release of Alvium G1-040m/c, G1-158m/c, G1-240m/c, G1-319m/c, G1-500m/c, G1-507m/c, G1-811m/c, G1-1236m/c, G1-1242m/c, G1-1620m/c, G1-2050m/c, G1-2050m/c, G1-2460m/c

New features

Initial feature set

Known issues

Alvium ID	Affected models	Description
251	G1-2050m/c	If ShutterMode is changed after image acquisition, the ExposureActive signal disappears.
253	All	Auto mode feature IntensityControllerOutliersDark does not work properly.
338	G1-500m/c, G1-2050m/c	If AcquisitionStop is executed shortly after AcquisitionStart , no image is transmitted.

Table 9: Known issues

Contact us

Website, email

General

www.alliedvision.com/en/contact

info@alliedvision.com

Distribution partners

www.alliedvision.com/en/avt-locations/avt-distributors

Support

www.alliedvision.com/en/support

www.alliedvision.com/en/about-us/contact-us/technical-support-repair-/rma

Current firmware and release notes

<https://www.alliedvision.com/en/support/firmware-downloads>

Offices

**Europe, Middle East, and Africa
(Headquarters)**

Allied Vision Technologies GmbH
Taschenweg 2a
07646 Stadtroda, Germany
T// +49 36428 677-0 (Reception)
T// +49 36428 677-230 (Sales)
F// +49 36428 677-28

Asia-Pacific**China**

Allied Vision Technologies
(Shanghai) Co., Ltd.
2-2109 Hongwell Int. Plaza
1602# ZhongShanXi Road
Shanghai 200235, China
T// +86 21 64861133

Singapore

Allied Vision Technologies Asia Pte. Ltd
82 Playfair Rd, #07-01 D'Lithium
Singapore 368001
T// +65 6634 9027

North, Central, and South America**Canada**

Allied Vision Technologies Canada Inc.
300 – 4621 Canada Way
Burnaby, BC V5G 4X8, Canada
T// +1 604 875 8855

USA

Allied Vision Technologies, Inc.
102 Pickering Way- Suite 502
Exton, PA 19341, USA
Toll-free// +1-877-USA-1394
T// +1 978 225 2030