

**PCN Title** FH55 Retaining Plate Add On

**Affected Products** Alvium CSI-2 cameras

**PCN Number** PCN2025-10-08

**PCN Issue date** 08.10.2025

**Contact** [Inside Sales Team](#)

**Change Classification**

Minor

**Change Type**

Add on

**Affected Products**

All Alvium CSI-2 models

**Change Description**

Every CSI-2 camera order includes a retaining plate as an add on

**Reason for Change**

FPC cables connected to Alvium CSI-2 cameras must be secured by a strain relief to avoid malfunctions or damage to the camera. If the FPC connector breaks, the camera must be replaced. Therefore, we recommend using the FH55 retaining plate only for evaluation purposes.

**Impact / Possible Successor**

The FH55 retaining plate can be used in addition to a strain relief, but it cannot replace a strain relief.

**First Ship Date**

20.10.2025

The information provided in this product change notification are subject to change without notice.

For the latest version of this document, please visit the Allied Vision [website](#).

**Support:**

In case of technical questions please contact our [Support Team](#)

**General inquiries:**

Please contact our [Inside Sales Team](#)