

**PCN Title** New Firmware v14.1 for Alvium Cameras, Version V00.14.01.d83c7207

**Affected Products** Alvium 1800 U, G1, and G5 cameras  
Exceptions: see below

**PCN Number** PCN2025-03-05 **PCN Issue date** 05.03.2025

**Contact** [Inside Sales Team](#)

#### Change Classification

Major

#### Change Type

Firmware Specification

#### Affected Products

Alvium 1800 U, G1, and G5 cameras

**Exceptions: X-050, X-131, and X-192, where X stands for either U/G1.**

#### Change Description

Resolved several known issues.

**Please also see the Firmware Release Notes for more details.**

#### Reason for Change

Optimization of the firmware

#### Impact / Possible Successor

Please check whether the changed camera behavior has an influence on your application!

#### First Ship Date

**CW14/2025**

If you want to receive the new firmware before this date for evaluation/testing, please contact our support team.

The information provided in this product change notification is subject to change without notice.

For the latest version of this document, please visit the Allied Vision [website](#).

#### Support:

In case of technical questions please contact our [Support Team](#)

#### General inquiries:

Please contact our [Inside Sales Team](#)